

OPTIMALISASI TERMINAL TIPE C SEMIN DI KABUPATEN GUNUNGKIDUL

KERTAS KERJA WAJIB

Diajukan Dalam Rangka Penyelesaian Program Studi Diploma III

Manajemen Transportasi Jalan

Guna Memperoleh Sebutan Ahli Madya Transportasi



Diajukan oleh :

FAJAR SAHLAN

NOTAR : 20.02 111

POLITEKNIK TRANSPORTASI DARAT INDONESIA – STTD

DIPLOMA III MANAJEMEN TRANSPORTASI JALAN

BEKASI

2023

**OPTIMALISASI TERMINAL TIPE C SEMIN
DI KABUPATEN GUNUNGKIDUL**

KERTAS KERJA WAJIB

**Diajukan Sebagai Salah Satu Syarat
Untuk Memperoleh Ahli Madya Pada Jurusan Diploma III
Manajemen Transportasi Jalan
(A.Md Tra)**



**Diajukan oleh :
FAJAR SAHLAN
NOTAR : 20.02.111**

**POLITEKNIK TRANSPORTASI DARAT INDONESIA – STTD
DIPLOMA III MANAJEMEN TRANSPORTASI JALAN
BEKASI
2023**

ABSTRACT

Semin Terminal is a Type C Terminal located in Gunung Kidul Regency and serves rural transportation. The condition of the terminal building consists of 70% main facilities and 10% supporting facilities and several building conditions need to be repaired. In addition, many facilities are not suitable for use and designation in accordance with Ministerial Regulation Number 24 of 2021 concerning the Implementation of Passenger Terminals and Ministerial Regulation Number 40 of 2015 concerning Service Standards for Road Transport Passenger Terminal Operations. As a result, Semin Terminal is still not optimal. The method used is the evaluation method for main facilities, supporting facilities and public facilities as the basis for calculating the area requirements for each facility. In addition, an evaluation was also carried out in the work area and terminal supervision, so that the existing conditions and proposals for terminal facilities could be obtained in the form of rearranging the facilities and functions of each terminal facility according to their proper use and restructuring the circulation of vehicles and people to avoid conflicts.

Keywords : *Terminal, Facility, Improvement, Arrangement, Evaluation, Circulation, Conflict*

ABSTRAK

Terminal Semin merupakan Terminal Tipe C yang terletak di Kabupaten Gunung Kidul dengan melayani perjalanan angkutan pedesaan. Kondisi bangunan terminal terdiri atas 70% fasilitas utama dan 10% fasilitas penunjang dan beberapa kondisi bangunan perlu dilakukan perbaikan. Selain itu banyak fasilitas yang tidak sesuai penggunaan serta peruntukannya sesuai dengan Peraturan Menteri Nomor 24 Tahun 2021 Tentang Penyelenggaraan Terminal Penumpang dan Peraturan Menteri Nomor 40 Tahun 2015 Tentang Standar Pelayanan Penyelenggaraan Terminal Penumpang Angkutan Jalan. Akibatnya Terminal Semin ini masih belum optimal. Untuk metode yang digunakan yakni metode evaluasi fasilitas utama, fasilitas penunjang dan fasilitas umum sebagai dasar

perhitungan kebutuhan luas fasilitas masing-masing. Selain itu, dilakukan juga evaluasi di daerah lingkungan kerja dan pengawasan terminal, sehingga dapat diperoleh kondisi eksisting dan usulan fasilitas terminal berupa penataan kembali fasilitas dan fungsi tiap fasilitas terminal sesuai dengan penggunaan yang semestinya serta melakukan penataan sirkulasi kendaraan dan orang agar terhindar dari konflik.

Kata Kunci : *Terminal, Fasilitas, Peningkatan, Penataan, Evaluasi, Sirkulasi, Konflik*